

DEPARTMENT HEALTH & WELFARE

DEBBY RANSOM, R.N., R.H.I.T - Chief

BUREAU OF FACILITY STANDARDS

3232 Elder Street

FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

P.O. Box 83720 Bolse, Idaho 83720-0036 PHONE: (208) 334-6626

JAMES E. RISCH - Governor RICHARD M. ARMSTRONG - Director

June 15, 2006

FLEGGE Ferren Weeks, Administrator Yellowstone Group Homes #1, #2, & #5 560 West Synnyside Lane Idaho Falls, ID 83401

RE: Provider Number 13G063, 13G064, and 13G067

Dear Mr. Weeks:

This is to advise you of the findings of the State Licensure and Medicare/Medicaid fire safety survey of the following ICFs/MR conducted on June 7, 2006.

Yellowstone Group Home #1 located at 3335 Springfield, Idaho Falls Yellowstone Group Home #2 located at 3245 Sunnybrook Lane, Idaho Falls Yellowstone Group Home #5 located at 4541 East Burke Drive, Ammon

Enclosed is a Statement of Deficiencies/Plan of Correction, form CMS-2567, and the State fire safety Statement of Deficiencies and Plan of Correction form listing fire and life safety deficiencies. In the space provided on the right side of each form, answer each deficiency and provide a date each will be corrected. Include in your plan of correction necessary corrective measures taken, provisions implemented to prevent re-occurrence, and department head/person responsible to monitor/assure that the deficiencies do not re-occur.

After you have answered and dated each deficiency, please sign and date the pages in the spaces provided. Retain one copy of each page for your files and return the originals to this office by Tuesday, June 27, 2006.

Thank you for the courtesies extended to me by you and your staff during my visit. Please call or write this office with any questions.

Sincerely,

CASWELL MERRITT, Health Facility Surveyor

Facility Fire Safety & Construction

CM/nm Enclosures DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

Printed: 06/14/2006 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING 01 - ENTIRE STRUCTURE B. WING 13G067 06/07/2006 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 4541 E BURKE DR YELLOWSTONE GROUP HOME #5 (BURKE) **AMMON, ID 83406** (X4) ID PREFIX SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X5) COMPLETION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE (EACH DEFICIENCY MUST BE PRECEEDED BY FULL PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) K 000 INITIAL COMMENTS K 000 This facility is a single story, type V (000) construction. It is fully sprinklered (except garage and attic areas) with Quick Response sprinkler heads. It is a rural location on a large lot. It has a complete fire alarm/smoke detection system. This home was built/completed on April 10, 1998. Currently it is licensed for 6 ICF/MR beds. The fire/life survey was conducted by Caswell Merritt and Christopher Laumann, Facility Fire Safety & Construction Section, Bureau of Facility Standards, Idaho Department of Health and Welfare. The following deficiencies are based on provisions set forth in the LIFE SAFETY CODE-2000 Edition for Residential Board & Care Chapter 33, Impractical Evacuation Capabilities. The attached PoC for all deficiencies listed. K0018 483.470(j)(1)(i) LIFE SAFETY CODE K0018 STANDARD Doors are provided with latches or other mechanisms suitable for keeping the doors closed. No doors are arranged to prevent the occupant from closing the door. 32.2.3.6.3. 32.2.3.6.4, 33.2.3.6.3, 33.2.3.6.4 Doors are self-closing or automatic closing in accordance with 7.2.1.8 RECEIVED Exception: Door closing devices are not required in buildings protected throughout by an approved JUN 2 6 2006 automatic sprinkler system in accordance with 32.2.3.5.1 and 33.2.3.5.2. FACILITY STANDARDS LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE (X6) DATE

deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that outer safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

Printed: 06/14/2006 FORM APPROVED OMB NO. 0938-0391

(X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION S'ATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION **IDENTIFICATION NUMBER:** COMPLETED A. BUILDING 01 - ENTIRE STRUCTURE B. WING __ 13G067 06/07/2006 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER YELLOWSTONE GROUP HOME #5 (BURKE) 4541 E BURKE DR **AMMON, ID 83406** (X5) COMPLETION DATE SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE PREFIX (EACH DEFICIENCY MUST BE PRECEEDED BY FULL PRÉFIX REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) K0018 Continued From page 1 K0018 This Standard is not met as evidenced by: Based on observation and review of monthly preventative maintenance records, one of three sleeping room doors was not smoke resistant. Findings Includes: During Facility tour on June 6, 2006 at 11:25 AM, the second bedroom door on the left when closed would not latch. This was not noted on the most recent monthly maintenance records. K0150 483.470(j)(1)(i) LIFE SAFETY CODE K0150 STANDARD New draperies, curtains, and other similar loosely hanging furnishings and decorations in board and care facilities are in accordance with provisions of 10.3.1. 32.7.5.1, 33.7.5.1 This Standard is not met as evidenced by: Based on interview and observation of privacy

was missed.

curtains while on tour of the facility, a privacy curtain was observed not to be labeled as fire

During the tour of the facility at 11:15 AM, one of three bedrooms with a privacy curtain in each bedroom was observed to have a privacy curtain that was not labeled as flame retardant or rendered flame resistant. Maintenance staff stated that new privacy curtains that were flame resistant were installed, however one bedroom

resistant or flame retardant.

Findings include:

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES Printed: 06/14/2006 FORM APPROVED OMB NO. 0938-0391

S'ATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		3	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - ENTIRE STRUCTURE		(X3) DATE SURVEY COMPLETED	
. !		13G067		B. WING _	B. WING		06/07/2006	
				PRESS, CITY, STATE, ZIP CODE				
YELLOWSTONE GROUP HOME #5 (BURKE) 4541 E BURKE DR AMMON, ID 83406								
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APPRO DEFICIENCY)	SHOULD BE COMPLETI		
K0150	0 Continued From page 2			K0150				
	Repeat deficiency from June 1, 2005.							
	.							
			44444					
			ann a tracament					
				***************************************	•			

Bureau of Facility Standards S' ATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING 01 - ENTIRE STRUCTURE B. WING 13G067 06/07/2006 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE YELLOWSTONE GROUP HOME #5 (BURKE) 4541 E BURKE DR **AMMON, ID 83406** SUMMARY STATEMENT OF DEFICIENCIES (X4) ID PROVIDER'S PLAN OF CORRECTION (X5) (EACH DEFICIENCY MUST BE PRECEEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PRÉFIX PREFIX COMPLETE TAG REGULATORY OR LSC IDENTIFYING INFORMATION) TAG CROSS-REFERENCED TO THE APPROPRIATE DATE DEFICIENCY) MM001 16.03.11001 Title and Scope MM001 These rules contain the official legal requirements and licensing standards for the administration of intermediate care facilities for the treatment of mental retardation (ICF/MR). These rules are to be cited as Idaho Department of Health and Welfare Rules, Title 03, Chapter 11, "Rules Governing Intermediate Care Facilities for the Mentally Retarded (ICF/MR)." This Rule is not met as evidenced by: The following State Licensure deficiency was cited during the annual fire safety survey of the above facility. MM346 16.03.11.110.06(g) In-House Check MM346 The facility must establish routine in-house test and check procedures covering alarm systems, extinguishment systems, and essential electrical systems. This Rule is not met as evidenced by: Based on surveyor observation, the TV located in the living room was plugged into an extension cord that was plugged into the wall electric receptacle. Findings Include: During the tour of the facility at 11:30 AM on June 6, 2006 the TV located in the living room was observed to be connected to electrical service with an extension cord. This was verified with the maintenance staff. RECEIVED JUN 2 6 2006 FACILITY STANDARDS LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE (X6) DATE STATE FORM ATG021199 If continuation sheet 1 of 1 June 21, 2006

Caswell Merritt, Health Facility Surveyor P.O. Box 83720 Boise, ID 83720–0036 JUN 2 6 2006
FACILITY STANDARDS

Dear Mr. Merritt:

Here are the plans of correction for the recent surveys of Yellowstone Group Homes #1, #2, and #5. I hope that the corrections we are making are satisfactory. If not, please contact me and we can discuss it further.

I appreciated your visit as always and am saddened by the fact that you won't be back to survey us. I've enjoyed your stories over the years as they were quite interesting. I wish you the very best for what life brings you now.

Sincerely

Ferren

Fire/life safety plan of correction for Yellowstone Group Home #5(Burke).

K0018 – This room is occupied by a client that has a history of slamming his door, which requires ongoing repair. The staff will be in-serviced on the importance of addressing this on all fire drills to assure that all doors are operating properly and those repairs, especially this particular door, are reported and completed. The home administrator will be responsible for doing this staff training. The home administrator will also be responsible for reviewing all reports to assure that it is being done. Revisions will be made to the Burke fire drill to specifically list this door and knob as it requires additional attention. This will be completed by 6/30/06.

K0150 - The privacy curtain in question was indeed one of our older ones that didn't contain a label. New privacy curtains had been purchased and the old ones were replaced throughout our homes. This one was inadvertently missed. The old one was discarded and was replaced immediately. The facility does have a supply of additional new curtains for future use. The home administrator has completed this by 6/21/06

MM346 - The staff will be in-serviced by the Burke home administrator regarding the need to use power strips rather than a simple extension cord. The cord has been replaced and the staff will be in-serviced by 6/30/06. To provide adequate check procedures in the future, the home environmental assessment form used at the home will have this specific concern listed so that needed corrections can be identified and completed. The regional administrator will make the changes to this form by 6/30/06.

Herren J. Weeks Regional administrator,